# Weathertzation Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/Client 50005DE0065/1

Work Order Type: Weatherization Audit Name: Audit DE0065

**CLIENT INFORMATION** 

Client Name: Address:

Client ID: Client 50005DE0065

Alt. Client ID:

**AGENCY INFORMATION** 

**Agency:** 50005DE **Agency Phone:** (901) 476-5226

**Address:** P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### <u>COMMENT</u>

Alt. Client ID:

### **Measures**

Measure 1 Repair broken panes - W2, W9 Comment			Componer	nts			Inspected		
					Estimated	d		Actual	
#	Material / Lab	or Description / Cor	mment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
0	ther Detail								
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
/	Measure 2	Infiltration Redctn			Componer	nts			Inspected
C		INFILTRATION ME							
		Add Doorsweeps - Fro Veatherstrip doors - I							
		Caulk Doors - Front a							
		ir Seal plumbing per							
		/rap and insulate (9)				- <b>f</b> :			
	6.0	aulk all windows on t	ne outside and c	n the ins	side for air ir <i>Estimated</i>		reduction	on <i>Actual</i>	
#	Material / Lab	or Description / Coi	mment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Miscellaneous	-		1			<i>y</i>		
	Supplies								
0	ther Detail								
L									
		-	_	Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 3 Fur comment	nace Tuneup			Componen	ts			Inspected
C	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Furnace Tuneup	Each	1					
2	Labor	Furnace Tuneup	Each	1					
C	Other Detail								
				Measur	e Sub Total:		] ;	Sub Total:	
	Measure 4 DW	/H Tank Insulation			Componen				Inspected
С	omment				Estimated			Actual	
<i>C</i>		The Tank Insulation  Description / Comment  DHW Tank Insulation	<i>Units</i> Each	<b>Qty</b> 1	-		Qty		Inspected Total
<b>C</b> # 1	Material / Labor Hot Water	Description / Comment			Estimated		Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated			Actual	

Measure 5 DWH Pipe Insulation			Componen	its			Inspected
Comment							
			Estimated	1		Actual	
# Material / Labor Description / Comm	ment Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Insulation DHW Pipe Insulati	ion Each	1					
2 Labor DHW Pipe Insulati	ion Each	1					
Other Detail							
		Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:							
Measure 6 Floor Ins. R-19 Comment			Componen		sq,ft		Inspected
Measure 6 Floor Ins. R-19 Comment			Estimated	1		Actual	
Measure 6 Floor Ins. R-19 Comment # Material / Labor Description / Comm		Qty	-		sq,ft  Qty		Inspected
Measure 6 Floor Ins. R-19 Comment	SqFt		Estimated	1		Actual	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation -	SqFt	Qty	Estimated	1		Actual	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation - Fiberglass Batts -	SqFt	Qty	Estimated	1		Actual	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation - Fiberglass Batts -	SqFt	Qty	Estimated	1		Actual	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation - Fiberglass Batts -	SqFt	<b>Qty</b> 1851	Estimated	1	Qty	Actual	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation - Fiberglass Batts -	SqFt	<b>Qty</b> 1851	Estimated Unit Cost	1	Qty	Actual Unit Cost	
Measure 6 Floor Ins. R-19 Comment  # Material / Labor Description / Comment  1 Insulation Floor Insulation - Fiberglass Batts - Other Detail	SqFt	<b>Qty</b> 1851	Estimated Unit Cost	1	Qty	Actual Unit Cost	

Measure 7 Atti	c Ins. R-30			Componen	its Main 1	851 sc	ą.ft	Inspecte	
Comment									
					<u> </u>	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1851						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Measure 8 Ref	rigerator Rplcmnt			Componen	nts				
Comment Seals a								Inspecte	
	ile ili verv bau Shabe - let	commend	replaci	na 20 cubic				Inspected	
# Material / Labor	ire iri very bad shape - rec	commend	replaci	ng 20 cubic	ft Fridge		Actual	Inspected	
# Waterial / Labor	Description / Comment	commend <i>Units</i>	replaci Qty	-	ft Fridge	Qty		Total	
				Estimated	ft Fridge	Qty	Actual		
0 Refrigerators		Units	Qty	Estimated	ft Fridge	Qty	Actual		
		Units	Qty	Estimated	ft Fridge	Qty	Actual		
0 Refrigerators		Units	Qty	Estimated	ft Fridge	Qty	Actual		
0 Refrigerators		Units Each	Qty 1	Estimated	ft Fridge		Actual		
0 Refrigerators  Other Detail		Units Each	Qty 1	Estimated Unit Cost	ft Fridge		Actual Unit Cost		
0 Refrigerators		Units Each	Qty 1	Estimated Unit Cost	ft Fridge		Actual Unit Cost		
0 Refrigerators  Other Detail		Units Each	Qty 1	Estimated Unit Cost	ft Fridge		Actual Unit Cost		

Measure 9 CO I	Monitor is Needed			Componen	its		ı	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail				1		1		
						] []		
			Measur	e Sub Total:		]	Sub Total:	
Field Notes:								
	or Barrier Needed sement/Crawlspace)			Componen	nts		ı	Inspected
Comment				Fatimata	,		Antural	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
Health and Safety Items	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								
		Work O	rder Gra	and Total:		Gran	d Total:	